

Stewart Lumber & Hardware

Engineered Lumber Pricing Page

| GLU-LAM Beams 24F-V4 | \$ / ft |
|--------------------------------------|---------|
| 3-1/2x7-1/2 GLB | \$ 9.44 |
| 3-1/2x9 GLB | 10.78 |
| 3-1/2x9-1/2 GLB | 12.38 |
| 3-1/2x10-1/2 GLB | 12.60 |
| 3-1/2x11-7/8 GLB | 14.25 |
| 3-1/2x13-1/2 GLB | 16.09 |
| 3-1/2x15 GLB | 18.23 |
| 3-1/2x16-1/2 GLB | 19.66 |
| 3-1/2x18 GLB | 22.74 |
| 5-1/2x7-1/2 GLB | 14.41 |
| 5-1/2x9 GLB | 16.24 |
| 5-1/2x9-1/2 GLB | 18.54 |
| 5-1/2x10-1/2 GLB | 18.93 |
| 5-1/2x11-7/8 GLB | 21.22 |
| 5-1/2x13-1/2 GLB | 24.39 |
| 5-1/2x15 GLB | 27.40 |
| 5-1/2x16-1/2 GLB | 30.17 |
| 5-1/2x18 GLB | 33.10 |
| 5-1/2x19-1/2 GLB | 38.08 |
| 5-1/2x21 GLB | 42.13 |
| 5-1/2x22-1/2 GLB | 45.53 |
| 5-1/2x24 GLB | 48.62 |
| 6-3/4x9 GLB | 24.00 |
| 6-3/4x10-1/2 GLB | 27.94 |
| 6-3/4x11-7/8 GLB | 32.00 |
| 6-3/4x13-1/2 GLB | 36.51 |
| 6-3/4x15 GLB | 40.64 |
| 6-3/4x16-1/2 GLB | 44.91 |
| 6-3/4x18 GLB | 50.36 |
| 6-3/4x19-1/2 GLB | 54.54 |
| 6-3/4x21 GLB | 59.56 |
| 6-3/4x22-1/2 GLB | 65.48 |
| 6-3/4x24 GLB | 70.62 |
| 8-3/4x10-1/2 GLB | 45.46 |
| 8-3/4x11-7/8 GLB | 50.12 |
| 3-1/2x9-1/2 HI-Clear II Treated GLB | 21.70 |
| 3-1/2x11-7/8 HI-Clear II Treated GLB | 26.47 |
| 3-1/2x14 HI-Clear II Treated GLB | 30.83 |
| 5-1/2x9-1/2 HI-Clear II Treated GLB | 29.89 |
| 5-1/2x11-7/8 HI-ClearII Treated GLB | 41.41 |
| 5-1/2x14 HI-Clear II Treated GLB | 51.56 |
| 5-1/2x16 HI-Clear II Treated GLB | 56.71 |
| 3-1/2 x 4-1/2 GL Column | 6.44 |
| 3-1/2 x 6 GL Column | 8.16 |
| 5-1/2x5-1/2 GL Column | 12.36 |
| 5-1/2 x 6 GL Column | 12.36 |

| LVL Gang-Lam | \$ / ft |
|-------------------|---------|
| 1.75 x 5.5 LVL | \$ 4.31 |
| 1.75 x 7.25 LVL | 5.47 |
| 1.75 x 9.5 LVL | 7.07 |
| 1.75 x 11.875 LVL | 8.81 |
| 1.75 x 14 LVL | 10.75 |
| 1.75 x 16 LVL | 12.73 |
| 3.5 x 9.5 LVL | 15.78 |
| 3.5 x 11.875 LVL | 19.28 |
| 3.5 x 14 LVL | 23.69 |
| 3.5 x 16 LVL | 29.81 |
| 5.25 x 5.5 LVL | 15.53 |
| 5.25 x 9.5 LVL | 25.63 |
| 5.25 x 11.875 LVL | 32.80 |
| 5.25 x 14 LVL | 39.45 |
| 5.25 x 16 LVL | 48.16 |
| 7 x 9.5 LVL | 37.38 |
| 7 x 11.875 LVL | 46.75 |
| 7 x 14 LVL | 57.27 |
| 7 x 16 LVL | 66.12 |

| LSL Beam | \$ / ft |
|-------------------|---------|
| 1.75 x 9.5 LSL | \$ 6.09 |
| 1.75 x 11.875 LSL | 7.63 |
| 1.75 x 14 LSL | 9.03 |
| 3.5 x 9.5 LSL | 12.18 |
| 3.5 x 11.875 LSL | 15.22 |

| LPI I-Joists | \$ / ft |
|-----------------------|---------|
| LPI-18 9.5 I-Joist | \$ 3.63 |
| LPI-18 11.875 I-Joist | 4.07 |
| LPI-20 9.5 I-Joist | 4.09 |
| LPI-20 11.875 I-Joist | 4.42 |
| LPI-20 14 I-Joist | 5.36 |
| LPI-32 11.875 I-Joist | 5.17 |
| LPI-32 16 I-Joist | 6.92 |
| LPI-36 11.875 I-Joist | 6.54 |
| LPI-36 14 I-Joist | 7.60 |
| LPI-56 11.875 I-Joist | 9.46 |
| LPI-56 14 I-Joist | 10.61 |
| LPI-56 16 I-Joist | 11.58 |